## Hi-Lo Gauge



## **OVERVIEW**

The Hi-Lo Gauge will measure the inside hi-lo, and can be left in place while the welder makes any necessary adjustments or reforms the pipe using a Sawyer external clamp. The gauge can also be used to measure the weld gap, to minimize weld rejections.



## FEATURES AND BENEFITS

- Measure inside pipe hi-lo and the weld gap
- Gauge can be left in place while making adjustments
- Range of primary colors and company name engraving available for minimum order of 500 gauges

## **ESTIMATED SHIPPING WEIGHT**

Model No.	Description	Weight
430	Hi-Lo Gauge	2.4 oz. 0.05 kg.

Follow us on social media and watch product videos on our YouTube channel Sawyer Mfg

